

What's changed in RoofWright 10.8.0?

We're constantly improving RoofWright based on feedback from our users and development requests.

The primary enhancement included in this version is *our **NEW Visionary Image Rendering**** feature, available with RoofWright Premium licenses.

****This feature requires that you have an internet connection at the point of image generation.***

A comprehensive list of other enhancements and bugfixes included in this version is detailed below:

Interface / General

- FB25996 – Duplicated warnings from Global Checks are now suppressed.
- FB27254 – Roof Tab view always is now always reset to 'Roof Editor' context on loading job or creating new job, to prevent toolbar buttons from appearing disabled.
- FB27280 -Freehand Editor left-most dimension no longer cropped from view.
- FB27368 – Ancillary Cost Group prefixed with Cost Category in ancillary configuration screen to negate ambiguity with groups that share common names.

Roof

- FB27250 – Roof sheets between splayed rafters now report the correct sheet width and sheet length.
- FB26125 – Changing tie-bar weight family now removes tie-bars and prompts the user of the change.

House Designer

- FB27148 – Fences can now be added to house designs.
- New Bungalow templates added.

Basework

- FB27148 – Door Pocket deductions are now applied to all frames next to brick pillars, not just those frames defined as doors.

Window Frames

- FB26787 – Custom width couplers are now correctly selected. Saved jobs containing custom width couplers no longer crash upon loading.


- FB27340 – Door thresholds change consistently when changed globally in Order Details. Overridden door thresholds can now correctly be returned back to the default / global option.
- FB27341 – Gable frame glazing now respects the minimum area to price, if configured against the glazing material.

Reports/Printing

- FB27190 – Dimensions on SheetData.Picture report field are no longer cropped.
- FB27261 – Report templates can now be password protected, to prevent unauthorised editing.
- FB27338 – WallSectionData report source now refreshes correctly after making design changes.
- FB27343 – Transom Splits dimension on FrameData.Picture report field are no longer cropped.
- FB27363 – Auto-Save images feature now works correctly.
- FB27376 – New Boolean report field **IsOrder** in DrawingData report source.

Order Details/ Preferences

- FB27305 – New system preference to allow default Frames view to be configured:



Functions

- FB27182 – NEW evaluable integer function **BifoldDoorLeafCount()**, which accepts two boolean parameters **IncludeFixedPanels** and **IncludeOtherOpenerTypes**, depending on the desired usage of the function.
- FB27231 – **ExternalWallArea** has been corrected in some cases where it was previously incorrect.